

MEYLE-ORIGINAL differential pressure sensor prevents costly subsequent damage!

MEYLE addresses the diesel exhaust emission controversy by making new additions to its range of sensors

Defective electronic parts can be costly: A failure of the differential pressure sensor (DP sensor) can cause irreparable damage to the diesel particle filter (DPF) and involve significant consequential costs in case of a turbocharger and engine breakdown.

However, replacing the entire diesel particle filter assembly is not always necessary: In many cases, it is sufficient – and also much more time and cost efficient – to replace only the sensor to remedy the problem! To help repair professionals and vehicle owners save precious time and money, MEYLE now offers the MEYLE-ORIGINAL DP sensor – an effective, yet low-cost alternative to the replacement of the entire particle filter assembly and OE solutions.

The MEYLE-ORIGINAL DP sensor at a glance:

- Manufactured to OE specifications
- **Full software compatibility:** Flawless communication between the MEYLE-ORIGINAL DP sensor and the control unit helps prevent false diagnosis and subsequent damage
- **A safe bet for customers and repair professionals:** The MEYLE sensor complies with the most demanding technical and legal requirements in place for diesel-powered vehicles and exhaust emission tests
- **Manufactured under ambient atmosphere conditions** the highly sensitive electronic components are engineered to meet the most stringent quality standards
- The range of MEYLE DP sensors caters for **26 million vehicles** the world over. New applications to be added in 2018.



MEYLE workshop advice:

1. To prevent subsequent damage to the DPF, the sensor must be replaced immediately if the control lamp on the dashboard signals sensor damage.
2. The MEYLE experts recommend that the differential pressure sensor always be replaced along with the diesel particle filter.
3. MEYLE recommends that the sensor pressure hose should be replaced along with the DP sensor.

MEYLE no.	Short no.	Application
114 801 0000	MEX0622	AUDI A3 [8P1, 8PA] [05/03-08/12], Q3 [8U] [06/11-/], TT [8J3, 8J9] [08/06-06/10]; SEAT Alhambra II [710] [06/10-05/11], Leon / Toledo/Altea [1P1, 5P2, 5P5] [03/04-05/10]; SKODA Fabia II [12/06-/], Octavia II [1Z_] [02/04-12/10], Roomster [03/06-03/10], Superb II [3T] [03/08-11/10], Yeti [5L] [05/09-/]; VW Amarok [09/10-/], Beetle [5C1] [04/11-/], CC [11/11-/], Caddy III [2KA, 2KB] [03/04-08/10], Caddy IV [05/15-/], Crafter [04/06-07/11], Golf V [1K1, 1K5, 5M1] [10/03-05/09], Golf VI [5K1, 517, AJ5] [10/08-11/13], Jetta III [1K2] [08/05-10/10], Jetta IV [162] [04/10-/], Passat [362, 365] [08/10-/], Passat [3C_] [03/05-10/11], Passat [A32] [04/11-12/14], Scirocco [137] [05/08-05/11], Sharan [7N] [05/10-05/12], Tiguan [09/07-08/09], Touran [1T3] [05/10-01/13], Transporter V [04/03-11/09], Transporter VI [04/15-/]
114 801 0001	MEX0623	AUDI A3 [8V1, 8VS, 8V7, 8PA] [04/12-/], A4 [8K2, 8K5, 8KH] [11/07-/], A4 [8W2, 8W5 B9] [05/15-/], A5 [8F, 8T] [06/07-/], A5 [F5] [06/16-/], A6 [4G2, 4G5, C7] [11/10-05/13], Q2 [09/16-/], Q3 [8U] [06/11-/], Q5 [8R] [11/08-/], Q5 [FY] [01/17-/], TT [8S] [09/14-/]; SEAT Alhambra II [710] [06/10-05/11], Ateca [06/16-/], Leon [5F] [09/12-/]; SKODA Kodiaq [03/17-/], Octavia III [5E3/5E5] [11/12-/], Superb II [03/15-/], Yeti [5L] [05/09-/]; VW Beetle [5C1] [04/11-/], CC [11/11-/], Caddy IV [05/15-/], Crafter [04/06-07/11], Golf VI [5K1, 517, AJ5] [10/08-11/13], Golf VII [08/12-/], Jetta IV [162] [04/10-/], Passat [A32] [04/11-12/14], Passat [B8] [08/14-/], Scirocco [137] [05/08-05/11], Sharan [7N] [05/10-05/12], Tiguan [09/07-08/09], Tiguan Allspace [BW2] [03/17-/], Tiguan II [02/16-/], Touareg [7P5] [01/10-/], Touran II [09/15-/]
114 801 0002	MEX0624	AUDI A3 [8P1, 8PA] [05/03-08/12], A4 [8EC, 8ED] [11/04-06/08], A6 [4F2, 4FH, 4F5] [05/04-08/11], TT [8J3, 8J9] [08/06-06/10]; SEAT Alhambra I [7V8, 7V9] [04/96-03/10], Ibiza III / Cordoba [02/02-11/09], Ibiza IV [6J1, 6J5, 6J8] [03/08-06/10], Leon / Toledo / Altea [1P1, 5P2, 5P5] [03/04-05/10]; SKODA Fabia II [12/06-/], Octavia II [1Z_] [02/04-12/10], Roomster [03/06-03/10], Superb II [3T] [03/08-11/10], Yeti [5L] [05/09-/]; VW Caddy III [2KA, 2KB] [03/04-08/10], Crafter [04/06-07/11], Eos [03/06-11/10], Golf V [1K1, 1K5, 5M1] [10/03-05/09], Golf VI [5K1, 517, AJ5] [10/08-11/13], Jetta III [1K2] [08/05-10/10], Passat [3C_] [03/05-10/11], Phaeton [3D] [04/02-/], Polo [9N_] [10/01-11/09], Scirocco [137] [05/08-05/11], Sharan [7M] [09/95-03/10], Tiguan [09/07-08/09], Touareg [7LA, 7L6, 7L7] [10/02-05/10], Touran [1T1, 1T2] [02/03-05/10], Transporter V [04/03-11/09]
11-14 801 0000	MEX0621	CITROËN Berlingo II [04/08-], C Elyse [11/12-], C-Crosser [02/07-], C2 / C3 I / Pluriel [02/02-09/05], C3 II [11/09-], C3 Picasso [02/09-], C4 Aircross [04/12-], C4 Cactus [09/14-], C4 Grand Picasso II [09/13-], C4 I / Coupe / Grand Picasso / Picasso / Stufenheck [11/04-1, C4 II / DS4 [11/09-], C5 I / C5 II [03/01-04/07], C5 III [RD_, TD_] [02/08-], C6 [09/05-], C8 [07/02-], DS3 [11/09-], DS5 [11/11-], Jumpy II [01/07-], Spacetourer [04/16-], Xsara Picasso [12/99-09/06]; FIAT Scudo II [270] [01/07-], Ulysse II [179] [08/02-06/11]; LANCIA Phedra [09/02-11/10]; PEUGEOT 1007 [04/05-], 2008 [03/13-], 206 [08/98-03/09], 207 [02/06-10/08], 208 [03/12-], 3008 [06/09-], 301 [11/12-], 307 [08/00-01/05], 308 [09/07-], 308 II [09/13-], 4007 [02/07-], 4008 [05/12-], 407 [05/04-12/09], 5008 [06/09-], 5008 II [12/16-], 508 [11/10-], 607 [02/00-07/04], 807 [06/02-05/06], Boxer III [04/06-], Expert II [01/07-], Expert III [04/16-], Partner II [04/08-], RCZ [03/10-]
36-14 801 0000	MEX0626	INFINITI EX [J50] [10/08-], FX II [10/08-], Q70 [Y51] [03/13-]; NISSAN Cube [Z12] [03/10-], Juke [06/10-], NV200 [02/10-], Navara [D40] [07/05-], Note [03/06-], Pathfinder [R51] [01/05-], Qashqai I [02/07-], X-Trail [T31] [03/07-]
714 801 0000	MEX0627	CITROËN Jumper III [04/06-]; FORD Fiesta VI [06/08-], Transit '02 [06/02-], Transit '06 [04/06-]; MAZDA 2 [DE] [10/07-]; PEUGEOT Boxer III [04/06-]; VOLVO C30 [10/06-12/12], C70 II [03/06-], S40 II / V50 [01/04-], S60 II / V60 [04/10-04/12], S80 II [03/06-], V70 III [08/07-], XC60 [05/08-12/10], XC70 II [08/07-]