

| Product info sh | eet | Robert Bosch | 0445010276 |
|--|-----|----------------------------|------------|
| Special tools needed? | No | | |
| | | | |
| | | | |
| | | | |
| Product specific information | | | |
| Programming | No | | |
| | | | |
| Unlocking | No | | |
| Adaption values reset | No | inviting on fac 20 seconds | |
| Bleed adjustment at mounting_1 | Yes | ignition on for 30 seconds | |
| | | | |
| | | | |
| adjustment at mounting 2 | | | |
| adjustment at mounting_2 | | | |
| | | | |
| | | | |
| | | Tightening torques | |
| Mounting fuelpump flange | | 18 Nm | |
| High Pressure pipe nuts | | 25 Nm | |
| | | | |
| | | | |
| | | | |
| | | Assembly instruction | ns |
| Recommendation: replace fuel filter Recommendation: replace drive plate | | | |
| Recommendation. replace (| | | |
| Core charge terms: | | | |
| -externally intact, | | | |
| -no mechanical damage, -not dismantled, | | | |
| -no heavy corrosion. | | | |