

| Product info sl | neet | Robert Bosch | 0445110212 |
|---|----------------|-------------------------|------------------|
| Special tools needed? | No | | |
| | | | |
| | | | |
| | | | |
| | - | | |
| | | duct specific inform | ation |
| Programming | Yes | IMA code (7 characters) | |
| | | | |
| Unlocking | No | | |
| Adaption values reset Bleed | No | | |
| adjustment at mounting_2 | | | |
| | | | |
| | | | |
| | | | |
| adjustment at mounting_2 | 2 | | |
| | | | |
| | | | |
| Tightening torques | | | |
| Injector/ retainingclamp | | 9 Nm (tighten 2 p | |
| High Pressure pipe nuts | | 23 Nm | |
| Inlet manifold | | M6: 10 Nm, M7: | 15 Nm, M8: 22 Nm |
| | | | |
| | | | |
| | | Assembly instructio | nc |
| Deulese estimation | | Assembly instructio | 113 |
| Replace sealing washer Recommendation: replace gasket inlet manifold | | | |
| | - gusket met m | | |
| Core charge terms: | | | |
| -externally intact, | | | |
| -no mechanical damage, | | | |
| -not dismantled, -no heavy corrosion. | | | |
| | | | |