

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

This alternator is commonly affected by a worn belt or tensioning issue which can result in the alternator pulley overheating and becoming discoloured/overheated.

Please check the alternator you are replacing for signs of rust or overheating before fitting the replacement alternator. If the alternator does display any of the above signs of failure the source of failure must be investigated and rectified before fitting the replacement alternator.

Failure to rectify this failure will resulting in the premature failure of the alternator and your warranty **may** be void.



FREE vehicle specific technical information available at autoelectro.co.uk



Vehicle specific information is available by searching the vehicle details via our website or scanning this QR code



