

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

THIS ALTERNATOR IS COMMONLY AFFECTED DUE TO BELT SLIP. IT IS HIGHLY RECOMMENDED THAT THE DRIVE BELT IS REPLACED WHEN FITTING THE ALTERNATOR TO AVOID PREMATURE FAILURE

FAILURE TO DO SO WILL RESULT IN DAMAGE TO THE DRIVE BELT AND OTHER COMPONENTS AND WILL CAUSE CHARGING FAULTS.

FREE vehicle specific technical information available at autoelectro.co.uk



Vehicle specific information is available by searching the vehicle details via our website or scanning this QR code

Fit and Forget!

