

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

PLEASE ENSURE THE DRIVE BELT IS REPLACED BEFORE FITTING THIS ALTERNATOR

There is a known fault with the drive belt system that can cause the premature failure of the alternator pulley and/or bearings.

Please inspect the alternator you are replacing for a failed pulley and/or oil contamination on the pulley and drive belt.

Other signs of failure are excessive fan belt dust on the front bracket of the alternator, polished pulley, noisy during operation and a very low charge rate.

The main cause of failure is due to excessive stretch wear on the drive belt and free play within the drive system.

If any of the above symptoms are present the drive belt, tensionor and other components within the drive belt system need inspecting a replacing if required, failure to do so will cause the failure of the replacement alternator and void your warranty.

FREE vehicle specific technical information available at autoelectro.co.uk



Vehicle specific information is available by searching the vehicle details via our website or scanning this QR code

Fit and Forget!

