

SPIDAN®
Original GKN Parts

Tech Tip

(EN) (DE)

Attention! Important flushing information

(EN) Flush the systems thoroughly

This application suffers from high wear rate that contaminates the oil. Failure to flush the system correctly and thoroughly before fitting a new pump will result in premature failure of the pump.

Failure due to contaminated oil is not covered by warranty!

(DE) Anlage sorgfältig spülen

Diese Anwendung leidet an starkem Verschleiss und verunreinigt dadurch das Öl. Wird die Anlage vor dem Einbauen einer neuen Pumpe nicht ordnungsgemäss und gründlich gespült, kann die neue Pumpe vorzeitig ausfallen.

Störungen durch verunreinigtes Öl fallen nicht unter die Garantie!

GKN Driveline Service GmbH Nussbaumweg 19–21 | 51503 Roesrath | Germany
www.gknautomotive.com | © GKN Automotive. All rights reserved.

Disclaimer of Liability

The information contained on this leaflet („Service“) is for general information purposes only. The application of any GKN Automotive product subject to the Service must be performed by certified professionals. GKN Automotive assumes no responsibility for errors or omissions in the contents on the Service. In no event shall GKN Automotive be liable for any special, direct, indirect, consequential, or incidental damages or any damages whatsoever, whether in an action of contract, negligence or other tort, arising out of or in connection with the use of the Service or the contents of the Service. GKN Automotive reserves the right to make additions, deletions, or modification to the contents on the Service at any time without prior notice.