LuK GearBOX, Part number: 462 0153 10

SCHAEFFLER



- This repair set does not include the sealing ring for the input shaft as this is part of the Concentric Slave Cylinder.
- The sealing rings of the MTX75 differential may vary depending on the application. When replacing, make sure which sealing rings (No. 7 and/or No. 8) have been installed originally.
- Repair instructions are available from the vehicle manufacturer.

No.	Description	Mounting Position	Part	Dimension (mm)
1	Main bearing input shaft	Engine side	Tapered roller bearing	27.50 x 57.18 x 19.85
2	Main bearing input shaft	Gearbox side	Tapered roller bearing	25.00 x 52.00 x 19.25
3	Main bearing output shaft	Engine side	Tapered roller bearing	27.50 x 66.00 x 20.50
4	Main bearing output shaft	Gearbox side	Tapered roller bearing	27.00 x 66.00 x 18.50
5	Main bearing differential	Engine side	Tapered roller bearing	41.00 x 68.00 x 18.00
6	Main bearing differential	Gearbox side	Tapered roller bearing	41.00 x 68.00 x 18.00
7	Seal rings differential*	Engine/Gearbox side	Shaft sealing rings	
8	Seal rings differential*	Engine/Gearbox side	Shaft sealing rings	
9	Seal ring speedometer drive		O-ring	

*Optional to use

Version: 1.112019