LuK GearBOX, Part number: 462 0195 10

SCHAEFFLER









- Manufacturer: Volkswagen Group Type: 0AH
 - Design: 5-speed manual transmission



- Information
- A typical failure is wear of the bearing shaft seat with double ball bearing which will be indicated by a rattling noise. This can result in the failure of the 5th gear needle roller bearing (see No. 4).
- Due to different vehicle applications of the VW 0AH transmission there are two LuK GearBOX sets (462 0195 10 / 462 0196 10). These sets differ in the gearbox-side bearing of the input and output shaft (double bearing with cast or sheet metal housing).
- The exact part number is determined by the transmission ID.
- Repair instructions are available from the vehicle manufacturer.

Box Content

•
•



No.	Description	Mounting Position	Part	Dimensions (mm)
1	Main bearing input shaft	Engine side	Roller bearing	24.10 x 47.00 x 17.70
2	Main bearing in-/output shaft	Gearbox side	Double ball bearing	172.00 x 108.00 x 38.00
3	Main bearing output shaft	Engine side	Roller bearing	32.00 x 55.00 x 18.00
4	Idler gear bearing and inner ring 5th gear	Gearbox side	Needle roller bearing	21.80 x 32.00 x 25.80
5	Main bearing differential	Engine side	Tapered roller bearing	41.00 x 68.00 x 18.30
6	Main bearing differential	Gearbox side	Tapered roller bearing	41.00 x 68.00 x 18.30
7	Seal ring input shaft	Engine side	Shaft sealing ring	
8	Seal rings differential	Engine/Gearbox side	Shaft sealing rings	
9	Seal cover 5th gear		Flat gaskets	
10	Seal bearing journals		O-rings	
11	Circlip 5th gear		Adjusting ring	17.70 x 2.00
12	Circlip 5th gear		Adjusting ring	17.70 x 2.10
13	Circlip 5th gear		Adjusting ring	17.70 x 2.20