

# CONTROL ARM SENSOR KITS

TECHNICAL INFO NO.1085

## VEHICLE MANUFACTURER / MODELS:

Fiat

Marea (185), Marea Weekend (185)

## APPLIES TO PART NO.:

No.	RUVILLE-No. Kit	RUVILLE-No. Lenker / Schwingarm	OE-No. Lenker / Schwingarm	OE-No. Sensor
1	935850E1	030 121 005N	46519893 46519894	46539832
2	935851E1	030 121 008D	46519897 46519898	46539833

## INSTALLATION INSTRUCTIONS:


Always check the struts/bushings of the wheel suspension and steering when replacing the control arm.

## IMPORTANT NOTE!

Note the specifications of the vehicle manufacturer!

In various vehicles, the ABS sensors have to be dismantled when replacing the control arm. Exposure to environmental influences and contact corrosion can also affect these sensors so that it is frequently impossible to remove them without causing any damage.

To avoid long down-times in the garage and warrant high customer satisfaction, Ruville the system specialist offers a kit consisting of control arm kit and sensor.



## INFORMATION

Corresponding spare parts can be found in our online catalogue at [www.ruville.de](http://www.ruville.de). Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.



RUVILLE

