

ContiTech

Elastic Belt 6PK1200 and 6PK1200 Standard

Problem:

The shift assembly of these items may cause serious problems in the belt, since cuts noise and even breakage of the belt.

Cause:

The fact that these items have the same measure facilitates to occur an incorrect application.

Solution:

Install correctly according to the application, because the conventional belt 6PK1200 applies to vehicles which require tensioner and has a dimension of 1200mm without being mounted, since the elastic 6PK1200 applies to vehicles which are not required in tensioners their systems, which are self-adjusting and applied only in VW vehicles, reach the size of 1200mm when assembled.

6 PK 1200



AUDI TT
NISSAN
SENTRA
TIIDA
RENAULT
MEGANE (NOVO)
MEGANE GRAN TOUR SW

6 PK 1200 ELÁSTICA



VOLKSWAGEN
NOVO GOL / FOX / SPACE FOX / POLO