

Product info sheet


Robert Bosch

0445010581

Special tools needed?

Yes

Fix pump-gearwheel when crankshaft is fixed



Product specific information

Programming

No

On the exchange pump is possibly 1 hole less than the original. This bolt must be left out.

Unlocking

No

Adaption values reset

No

Bleed


Yes

Pre-fill with fuel

adjustment at mounting_1

Yes

Respect timing mark pump sprocket because of pressure-pulse timing



adjustment at mounting_2

--

Tightening torques

Mounting fuel pump flange

8 Nm

Pump pulley/sprocket

65 Nm

Mounting fuel pump bracket

19 Nm

Assembly instructions

Recommendation: replace fuel filter

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.