

Product info sheet

Robert Bosch

0445110038

Special tools needed?

No

Injectors can be very stuck. Please contact us if you don't have the right equipment.

Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed

Yes

Ignition for 30 s, bleedscrew open.

adjustment at mounting_1

No

adjustment at mounting_2

Tightening torques

Injector/ retainingclamp

1: Nuts both sides: 6 Nm 2: Flywheelside: +360°

High Pressure pipe nuts

25 Nm

Assembly instructions

Replace sealing washer

Recommendation: use ceramic grease

Recommendation: replace sealing ring

Replace bolts/studs and nuts

Recommendation: clean bolt hole

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

