

## Product info sheet

Robert Bosch

0445110048

Special tools needed?

No

## Product specific information

Programming

No

Classification code

All new and overhauled injectors will be considered as class B0.

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting\_1

--

adjustment at mounting\_2

## Tightening torques

Injector/ retaining clamp

10 Nm (2 pieces tighten equally)

High Pressure pipe nuts

30 Nm

Inlet manifold

M6: 10 Nm, M7: 15 Nm, M8: 22 Nm

## Assembly instructions

Replace sealing washer

Recommendation: replace gasket inlet manifold

### Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

