

Product info sh	eet	Robert Bosch	0445110078
Special tools needed?	No		
Product specific information			
Programming		lassification code	
		all cylinders equal class 1, 2 or 3 when partnr. e exchanged. When more than 2 mounted. trea	
Unlocking	No		A CONTRACTOR OF CONTRACTOR
Adaption values reset	No		ARTIKELCODE
Bleed	No		
adjustment at mounting_1			
adjustment at mounting_2			
Tightening torques			
High Pressure pipe nuts		28 Nm	
Injector/ retainingclamp		D5244T >T3: 28Nm, D5	244T4 > T9: 13 Nm
Assembly instructions			
Replace tension bolts			
Replace sealing washer			
Core charge terms:			
-externally intact,			
-no mechanical damage,			
-not dismantled,			
-no heavy corrosion.			