

-no heavy corrosion.

<b>Product info sh</b>	neet	Robert Bosch	0445110135
Special tools needed?	No		
	Pr	oduct specific informa	ation
Programming	Yes	IMA code (8 characters)	TO THE REAL PROPERTY OF THE PR
		Attention; cylinder 1 is flyv	
Unlocking	No		
Adaption values reset	No		CAN READ
Bleed	No		
adjustment at mounting_1	No		
adjustment at mounting_2		1	
adjustifient at modifing_2		<u> </u>	
		Tightening torques	
Injector/ retainingclamp		4 Nm + 65°	//
High Pressure pipe nuts		23 Nm	
Bolts EGR		10 Nm	A = A
		Assembly instruction	ns
Replace sealing washer		•	
,			
O		N. C. L.	
Core charge terms: -externally intact,			
-no mechanical damage,			
-not dismantled			