

Product info sheet

Robert Bosch

0445110166

Special tools needed?

No

Product specific information

Programming

Yes

IMA code (6 characters)

When 7 characters is demand by programming calibration on vehicle, enter "0" on last position.

Unlocking

No

Adaption values reset

No



Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2



Tightening torques

Injector/ retaining clamp

7 Nm + 90° + 90°

Assembly instructions

Recommendation: replace fuel filter

Recommendation: use ceramic grease

Replace sealing washer

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

