

Product info sh	eet	Robert Bosch	0445110340
Special tools needed?	No		
Product specific information			
Programming		MA code (9 characters)	
Unlocking	No		
Adaption values reset	No		The second secon
Bleed		Jse manual pump on vehicle	
adjustment at mounting_1	No		
adjustment at mounting_2			
Tightening torques			
Injector/ retainingclamp		7 Nm + 85°	
High Pressure pipe nuts		25 Nm	
Assembly instructions			
Replace sealing washer	AJ		tion: replace fuel filter
Replace sealing washer		Recommenda	tion. replace the inter
Core charge terms:			
-externally intact,			
-no mechanical damage,			
-not dismantled, -no heavy corrosion.			