

Product info sheet	Robert Bosch	0445110418
Special tools needed? No		
Product specific information		
Programming Yes	IMA code (8 characters)	95318 1731 1602 ₩ 🔾
Unlocking No		
Adaption values reset No		5086435 28058 58058
Bleed		
adjustment at mounting_1 No adjustment at mounting_2		
Injector/retainingclamn	Tightening torques 28 Nm	/
Injector/ retainingclamp High Pressure pipe nuts	25 Nm	
Assembly instructions Replace sealing washer		

Core charge terms:

- -externally intact,
- -no mechanical damage,

Recommendation: replace fuel filter

- -not dismantled,
- -no heavy corrosion.





