

Product info sheet

Robert Bosch

0445115007

Special tools needed?

No

Injectors can be very stuck. Please contact us if you don't have the right equipment.

Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No

Bleed


No

adjustment at mounting_1

No

adjustment at mounting_2

--



Tightening torques

Injector/ retaining clamp

35 Nm

High Pressure pipe nuts

35 Nm

Assembly instructions

Replace sealing washer

Replace tension bolts

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.