

Product info sheet		Robert Bosch		044	5115063
Special tools needed?	No				
Product specific information					
December		-		.1011	
Programming	Yes	IIVIA code (7 characters)		
D. L. Drac	No				IMA
Unlocking Adaption values reset	No No				AND
Bleed	No				
adjustment at mounting_1					
adjustment at mounting_2					
Tightening torques					
Injector/ retainingclamp		J	7 Nm + 90° + 90°		
High Pressure pipe nuts			Injector: 33 Nm, Rai	l: 27 Nm	
					<u>A</u>
Assambly instructions					
Assembly instructions					
Replace tension bolts Replace sealing washer					
Core charge terms:					
-externally intact,					
-no mechanical damage,					
-not dismantled, -no heavy corrosion.					
110 Heavy Collosion.					