

Product info sh	eet	Denso	095000-6490
Special tools needed?	No		
Product specific information			
Programming	Yes	ID code (30 characters)	
Unlocking	No		
Adaption values reset	No		
Bleed	No		
adjustment at mounting_1	No		JOHN DEERE
			particular injector. It is very important that you correctly groupes the engine with injector collisation mater, but douby no cash result in parties to the original Anno Energy and Continues and Con
			Culy cent for lost inglish digits of the sentiments.  If more than gight dept in we contend, the triminals may not be recepted.  From the content of the content of the triminals may not be recepted.
		_	TOTAL TO A STATE AND A STATE A
adjustment at mounting_2			
		Tightening torq	
Bushing inlet pipe		1: 5 Nm 3: 3	5 Nm
Injector/ retainingclamp		2: 47 Nm	
High Pressure pipe nuts		27 Nm	
Electrical connectors injector 2 Nm			
		Assembly instruc	tions
Buden B		Assembly instruc	
Replace sealing washer		Recomm	endation: replace fuel filter
Replace inlet pipe	coaling ring		
Recommendation: replace	scanng mig	; 	
Core charge terms:			
-externally intact,			
-no mechanical damage,			
<ul><li>-not dismantled,</li><li>-no heavy corrosion.</li></ul>			