



AUTOELECTRO

Since 1986

STARTER MOTORS & ALTERNATORS


IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

This unit is commonly returned for failure due to fluid contamination. Depending on the vehicle there are numerous sources of the fluid leak which can contaminate the unit.

It is critical that you visit our website to obtain information and carry out further investigations to locate the leak and rectify it prior to fitting the replacement unit. Failure to do so will cause the replacement unit to fail prematurely and will invalidate your warranty.

Look out for fluid residue, rust build up, distinctive smell and possible burning smell.

FREE vehicle specific technical information available at autoelectro.co.uk



Vehicle specific information is available by searching the vehicle details via our website or scanning this QR code



Fit and Forget!