

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

There is a known fault with some vehicles that this alternator is fitted to which cause the cooling fan continuously run on after a replacement alternator is fitted

The cause of the fault is the multi plug for the water pump which has either not been plugged in or is not connected correctly. Please ensure that the plug is fitted and secured.

Once the plug has been connected further re-programming or fault code clearing may be required.

Failure to rectify the above fault will result in the battery discharging and causing excessive load to be exerted to the alternator and resulting in the premature failure of the unit.

FREE vehicle specific technical information available at autoelectro.co.uk



Vehicle specific information is available by searching the vehicle details via our website or scanning this QR code



