

## MEYLE-HD stabilizer kits come with a full set of mounting parts and a 4-year warranty.

To fit SEAT Ibiza | Skoda Fabia | VW Polo

On some Volkswagen Group models stabilizer thrust plates may break owing to age, causing the stabilizer mounts to lose their lateral guiding. In addition, exposure to environmental influences such as moisture, road salt and dirt gradually eats away at the protective coating of the stabilizer increasing the risk of corrosion between the stabilizer and mount. The result: irritating noise during compression and rebound and when cornering.

Once a component does fail, it almost always causes damage to adjacent parts. This is why MEYLE engineers strongly recommend that all system-relevant components be replaced at once. MEYLE now offers stabilizer kits in HD quality with a four-year warranty including all parts necessary for highquality repairs in compliance with work time allowances.

Supplied in a cardboard box the MEYLE-HD stabilizer kits contain the stabilizer, the MEYLE-HD stabilizer links, the stabilizer mount and a full set of mounting hardware. MEYLE-HD stabilizer kits – for cost-effective repairs at their simplest!



Stabilizer kit MEYLE no. (Short no.)	included stabilizer link MEYLE no. (Short no.)	included stabilizer mount MEYLE no. (Short no.)
100 653 0002/HD (MCX0175HD)	116 Ø6Ø ØØØØ/HD (MSLØ1Ø7HD)	100 411 0050/S (MSB0088)
100 653 0003/HD (MCX0176HD)	116 060 0000/HD (MSL0107HD)	100 411 0051/S (MSB0090)
100 653 0004/HD (MCX0177HD)	116 060 0000/HD (MSL0107HD)	100 411 0052/S (MSB0092)

More stabilizer kits will be available shortly.