

Product info sheet

Robert Bosch

0414693006

Special tools needed?

No



Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2

Tightening torques

Mounting fuel pump bracket

10 Nm + 50 Nm

Assembly instructions

Recommendation: replace sealing ring

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.