

Product info sheet		Robert Bosch	0445010011
Special tools needed? Pulling out and fixing the	Yes oump drivewh	eel	
	Pro	oduct specific inform	ation
Programming	No		
Unlocking	No		
Adaption values reset	No		
Bleed	Yes	ignition on for 30 seconds	
adjustment at mounting_1			
adjustment at mounting_2	2		
			
		Tightening torques	
Mounting fuelpump flange		24 Nm	/
Pump pulley/sprocket		65 Nm	
High Pressure pipe nuts Cover / dustcap		20 Nm 30 Nm	
cover / dasteap			
		Assembly instructio	ns
Recommendation: replace	fuel filter	•	
Recommendation: replace	gasket flange		
Core charge terms:			
-externally intact,			
-no mechanical damage,			
-not dismantled,			
-no heavy corrosion.			