

Product info sheet	Robert Bosch	0445010018
Special tools needed? No		
Pr	oduct specific informa	ition
Programming No		
Unlocking Adaption values reset No		
Bleed Yes	Use manual pump on vehicle	
adjustment at mounting_1 No		
adjustment at mounting_2		
	Tightening torques	
Pump pulley/sprocket	50 Nm	
Mounting fuelpump flange	35 Nm	
		4-1-1-1
	A	
December detions replace first filter	Assembly instruction	1S
Recommendation: replace fuel filter		
Core charge terms:		
-externally intact,		
-no mechanical damage, -not dismantled,		
-no heavy corrosion.		