

-not dismantled,-no heavy corrosion.

Product info s	heet	Robert Bosch	0445110044
Special tools needed?	No		
	Pr	oduct specific informa	tion
Programming	No	Graded; use identical	
		All Buchli or Bosch Exchange injective Existing injectors are tagged with paintdot:	ctors use code "2".
Unlocking	No		
Adaption values reset	No		
Bleed	No		
adjustment at mounting_	1		
adjustment at mounting_	2		_
		Tightening torques	
Injector/ retainingclamp		30 Nm	
High Pressure pipe nuts		28 Nm	
riigii i ressure pipe nuts		20 11111	
			Allering
		Accombly instruction	
		Assembly instruction	5
Replace sealing washer			
Core charge terms:			
externally intact,			
no mechanical damage,	,	0	