

Product info sheet

Robert Bosch

0445110076

Special tools needed?

No

Product specific information

Programming

Yes

Graded; use identical

All Buchli or Bosch Exchange injectors use code "Y"

Programming only necessary when mounted injectors had code "X" or "Z".

Unlocking

No

Adaption values reset

No


Bleed

No

adjustment at mounting_1

--

adjustment at mounting_2



Tightening torques

Injector/ retaining clamp

30 Nm

High Pressure pipe nuts

28 Nm

Assembly instructions

Replace sealing washer

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

