

## Product info sheet

Robert Bosch

0445110084

Special tools needed?

No

## Product specific information

Programming

Yes

IMA code (6 characters)

Unlocking

No

Adaption values reset

No


Bleed

No

adjustment at mounting\_1

--

adjustment at mounting\_2



## Tightening torques

Injector/ retaining clamp

1: Nuts both sides: 6 Nm 2: Flywheelside: +360°

High Pressure pipe nuts

25 Nm

## Assembly instructions

Replace bolts/studs and nuts

Replace sealing washer

### Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

