

-no mechanical damage,

-not dismantled,-no heavy corrosion.

Product info sh	eet	Robert Bosch	0445110199
Special tools needed?	No		
	Pro	duct specific informa	tion
Programming	No		
Unlocking	No		
Adaption values reset	No		
Bleed	No		
adjustment at mounting_1			
adjustment at mounting_2			
adjustment at mounting_2			
		Tightening torques	
Injector/ retainingclamp		7 Nm + 90° + 90°	
High Pressure pipe nuts		23 Nm	
			A
		Assembly instruction	IS
Replace sealing washer			
Replace tension bolts			
Recommendation: use cera	mic grease		
Core charge terms:			
-externally intact,			