

Product info sheet

Robert Bosch

0445110201

Special tools needed?

No



Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

--

adjustment at mounting_2

Tightening torques

Injector/ retaining clamp

7 Nm + 90° + 90°

High Pressure pipe nuts

22 Nm

Inlet manifold

10 Nm

Assembly instructions

Replace tension bolts

Replace sealing washer

Recommendation: use ceramic grease

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

