

Product info sheet

Robert Bosch

0445110468

Special tools needed?

No

Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2



Tightening torques

Injector/ retaining clamp

8 Nm + 270°

High Pressure pipe nuts

28 Nm

Assembly instructions

Replace sealing washer

Recommendation: replace fuel filter

Replace tension bolts

Recommendation: replace sealing ring

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

