

Product info sh	eet	Robert Bosch	0445110646
Special tools needed?	No		
Programming Unlocking Adaption values reset Bleed adjustment at mounting_1 adjustment at mounting_2		ct specific information MA code (7 characters)	
Tightening torques			
Injector/ retainingclamp High Pressure pipe nuts		8 Nm + 180° 25 Nm	
Assembly instructions			

Replace sealing washer

Replace tension bolts

Recommendation: use ceramic grease

Core charge terms:

- -externally intact,
- -no mechanical damage,
- -not dismantled,
- -no heavy corrosion.





