

<b>Product info s</b>	heet	Robert Bosch	0445120008	
Special tools needed?	Yes			
	Pro	duct specific info	rmation	
Programming	No			
Unlocking	No			
Adaption values reset	No			
Bleed adjustment at mounting	Yes 1 No			
adjustifient at mounting	_1 110			
adjustment at mounting	_2			
		Tightening torq	ues	
Injector/ retainingclamp	)	49 Nm		
High Pressure pipe nuts		25 Nm		
Fuel connection		10.11		1
Bolts valve cover		12 Nm		] 1
				]
		Assembly instruc	tions	_
Replace sealing washer		<u> </u>	tension bolts	
Recommendation: replace	ce gasket inlet m		bolts/studs and nuts	
Recommendation: repla	ce fuel filter			
Core charge terms:				
externally intact,				
no mechanical damage	2,			
not dismantled, no heavy corrosion.				