



Product info sheet

Robert Bosch

0445120067

Special tools needed?

No

Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2

Tightening torques

Injector/ retaining clamp

5 Nm + 120°

High Pressure pipe nuts

25 Nm

Assembly instructions

Recommendation: replace fuel filter

Replace sealing washer

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.