

Product info sh	eet	Rober	t Bosch	0470004007	
Special tools needed?	Yes				
 Support the engine to dis Fix crankshaftpin and tim Puller for camshaft gearv 	ing plate in ca				
Product specific information					
Programming	No				
First			ontrol unit and motor cont r: kev power on 30 sec ke		
Unlocking	Yes		r will be delivered		
Adaption values reset	No				
Bleed	Yes	Help with r	nanual pump befor	e fuel filter	
adjustment at mounting_1	Yes				
Injection point set by timing pin					
adjustment at mounting_2 Camshaft with special tools	Yes (fixed cranks)	naft)			
Tightening torques					
Mounting fuelpump flange 20 Nm					
Pump pulley/sprocket			4 x 33 Nm (chainwheel) + 3 x 42 Nm (beltwheel)		
Tensioner timingbelt, -chain			15 Nm		
Camshaft pulley/sprocket			50 Nm		
Engine mount			Nuts: 83 Nm, Bolts: 50 Nm		
High Pressure pipe nuts			28 Nm		
Assembly instructions					
Recommendation: replace gasket flange					
Recommendation: replace					
<u>Core charge terms:</u> -externally intact,					

-no mechanical damage, -not dismantled,

-no heavy corrosion.