

-no heavy corrosion.

<b>Product info s</b>	heet	Robert Bosch	0470504027
Special tools needed?	Yes		
1: Turn crankshaft to TDC 2: Fix pump gear and sub 3: After mounting pump	gear with fitti		E
All VA	Pro	oduct specific informat	ion
Programming	No		M6 × 1mm —
Unlocking	No		Ø 10mm 20mm
Adaption values reset	No		77
Bleed	Yes	Help with manual pump before	fuel filter
adjustment at mounting_	1 Yes		"0"
Injection point pre-set on			E.M.
Timingsprocket with timi	ng mark		<b>7</b>
adjustment at mounting_	2		н
		Tightening torques	
Cover / dustcap		39 Nm	7
High Pressure pipe nuts		23 Nm	4.000
			4
Turn engine only clockwis	se	Assembly instructions	
Core charge terms: -externally intact, -no mechanical damage -not dismantled,	,		