



Product info sheet

VDO

5WS40000-Z

Special tools needed?

No

Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2

--

Tightening torques

High Pressure pipe nuts

25 Nm

Injector/ retaining clamp

30 Nm

Assembly instructions

Replace sealing washer

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.