



Product info sheet

VDO

5WS40148-Z

Special tools needed?

No

Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2

Tightening torques

Injector/ retaining clamp

15 Nm + 70°

High Pressure pipe nuts

23 Nm

Assembly instructions

Replace tension bolts

Replace sealing washer

Recommendation: use ceramic grease

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.