

-no heavy corrosion.

Product info s	heet	Delph	İ	R	00501Z	
Special tools needed?	Yes					63
Mounting tools to fix inje	ctors while tig	hten / loosen inj	ectors			
	Pr	oduct spec	cific infor	mation		CODE
Programming	Yes	C2I code (1	6 characters)		6C327497	3D7DCA8D U
	W	hen the injector is over	hauled; the code on	the sticker must be us	ed.	10-9/546-88
Unlocking	No				> © € € 5 € 5 € 5 € 5 € 5 € 5 € 5 € 5 € 5	R005012 I
Adaption values reset	No					TO SEE
Bleed	Yes	Start 30 sec	. with detache	ed connectors		
adjustment at mounting_	1 Yes					
adjustment at mounting_	2					
		Tighten	ing torqu	ies		
Injector/ retainingclamp			52 Nm			
High Pressure pipe nuts			40 Nm			
		Assambly	, in at rulet	iono		
Replace sealing washer		Assembly	y mstruct	.10115		
Recommendation: replac	e seals in valv	e cover				
Core charge terms: -externally intact, -no mechanical damage	,					