

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS
PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE
PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY


This alternator is commonly misdiagnosed as being faulty.


This alternator requires a permanent battery supply to the 'S' terminal and this must be around 12.4V

If the alternator is not receiving the correct voltage to the 'S' terminal it can cause the alternator to charge with the light on or overcharge.

Please inspect the wiring for any breaks, corrosion etc. and ensure that the voltage at the 'S' terminal and the battery is around 12.4v. An undercharged or faulty battery will cause the above faults to occur.

Failure to rectify this vehicle fault can cause the premature failure of the alternator and invalidate your warranty.





## FREE vehicle specific technical information available at autoelectro.co.uk



Vehicle specific information is available by searching the vehicle details via our website or scanning this QR code



