




RML 75267 CP15



RML 75267 CP15



| Cross References |                 |
|------------------|-----------------|
| CF Gomma         | 1 T 323-32      |
| Contitech        | 4156NP15        |
| Dunlop           | D12B16          |
| Firestone        | 1T 15 M-6       |
| Firestone        | W01 M58 9361    |
| Goodyear         | 1R12-130        |
| Phoenix          | 1 DK 23 K 9361  |
| Taurus           | KR 50-28        |
| Vibracoustic     | V 1DK 23 K 9361 |

RML 75267 CP15



| OEM Part Number |          |
|-----------------|----------|
| Fruehauf        | M001472  |
| Hendrickson     | HA100001 |
| ROR Meritor     | 21215761 |
| SMB Fruehauf    | UJB0207  |
| Weweler         | US35864  |