



OPEL ASTRA J (7/11->)

EUROSTAMP S.r.l.
Via Airauda, 1 – 10044 Pianezza (TO) ITALY

Das Unternehmen erhält mit dem Zertifikat Nr. B 15 07 66697 026.010 entsprechend dem dazugehörigen Prüfbericht das Recht, sein nachfolgend beschriebenes Produkt mit dem abgebildeten Prüfzeichen des

TÜV SÜD AUTOMOTIVE GmbH.

zu Kennzeichnung:



Dieses Produkt erfüllt die grundlegenden Anforderungen an Paßgenauigkeit, Passform und Material-/Splitterprüfung gemäß den Anforderungen der TÜV SÜD AUTOMOTIVE GmbH.

Produktbeschreibung: Stoßstange vorne Grundiert – mit 2 Löchern für die Sensoren

101.38.9130

den 11/06/2015

TÜV SÜD AUTOMOTIVE GmbH

Zertifikat – Nr.: B 14 11 6697 021.011
Certificate – No.

Anhang 1 Fotodokumentation
Annex 1 Photo documentation

Tested product



Original Equipment



Zertifikat – Nr.: B 14 11 6697 021.011
Certificate – No.

Original Equipment



Tested product



Zertifikat – Nr.: B 14 11 6697 021.011
Certificate – No.

Original Equipment



Tested product



Zertifikat – Nr.: B 14 11 6697 021.011
Certificate – No.





Original Equipment









Tested product



Zertifikat – Nr.: B 14 11 6697 021.011
Certificate – No.

Original Equipment	Tested product
	
	

Zertifikat – Nr.: B 14 11 6697 021.011
Certificate – No.

Original Equipment	Tested product
 A close-up photograph of a metal component, likely a pressure washer trigger gun. It features a central circular trigger button, two rows of spray lance connectors on either side, and a small label with the number '13374455'.	 A close-up photograph of a similar metal component. It has a central circular trigger button, two rows of spray lance connectors, and a label with the number '13374455' and the letters 'R H'.
 A close-up photograph of the back of the original equipment. It shows a rectangular mounting bracket with a central circular opening and two rows of spray lance connectors.	 A close-up photograph of the back of the tested product. It shows a similar mounting bracket with a central circular opening and two rows of spray lance connectors. The label '13374455' and 'R H' are visible.
 A close-up photograph of the central circular trigger button of the original equipment, showing its metallic finish and central opening.	 A close-up photograph of the central circular trigger button of the tested product, showing its metallic finish and central opening.