



## SERVICE INFO – INA 0133



# Poluklackalica 423 0076 10

## Vizualna izmjena

Proizvođač: Audi

Modeli: A4 (8K2, B8), A4 Avant (8K5, B8),  
A4 Allroad (8KH, B8), A5 (8T3),  
A5 Sportback (8TA),  
A5 Cabriolet (8F7),  
A6 (4F2, C6/4G2, C7),  
A6 Avant (4F5, C6/4G5, C7),  
A8 (4E\_/4H\_), Q5 (8R), TT (8J3),  
TT Roadster (8J9)

Motori: 2.0 TFSI, 2.8 FSI, 3.2 FSI

Kat. Br.: 423 0076 10

OE broj: 06E 109 409 M  
06E 109 409 K



Slika 1: 423 0076 10 - Stara izvedba (lijevo) i nova izvedba (desno)

Za gore navedene modele izmijenjen je dizajn klackalice ventila. OEM (originalni proizvođač opreme) dodijelio je klackalici ventila novi broj dijela.

S obzirom na to da se ova dva dizajna razlikuju samo u izgledu, Schaeffler Automotive Aftermarket koristit će broj prethodnog dijela 423 0076 10 i za novi dizajn.

S tehničke strane moguće je miješano montiranje oba dizajna!

Pridržavajte se uputa proizvođača vozila!

Odgovarajući rezervni dijelovi i tehničke informacije mogu se pronaći na [www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com) ili na [www.RepXpert.com](http://www.RepXpert.com).

### Za daljnje informacije:

Phone: +44 (0) 14 32 264 264\*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

[www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com)

**SCHAEFFLER**  
AUTOMOTIVE AFTERMARKET



INA 0133