


RML 78263 C



●
bolt or stud

○
hole

⊗
threaded hole

⊗
combinations stud

⊗
air inlet



RML 78263 C



Cross References	
Goodyear	1R11-847





RML 78263 C



OEM Part Number	
Hendrickson	HS508263
Mercedes (Actros)	9423205921

